MOVEABLE SHELVING PROJECT OBSERVATIONS AS OF 8-16-71

- 1. Bay 1, Sect. 2, Aisle 5 -- Light farthest from center aisle keeps going off, possibly needs new ballast.
- 2. Bay 1, Sect. 1, Aisle 6, Plastic Safety Housing broken.
- 3. Bay 1, Sect. 1 -- Motor covers do not cover opening completely.
- 4. Bay 1 & 2, Sect. 2 & 4 -- Mosler alarm boxes hidden behind stationary.
- 5. Bay 1, Sect. 1, Aisle 1, Stationary -- Not room for boxes because of wires. In fact, there is a serious design problem on all equipment and wires on top shelf for all of Bay 1 that will have to be resolved before work continues on next bays: arm extender placement, excess wire in way of boxes and wires over edge of sharp metal.
- 6. Bay 1, Sect. 1 & 2 -- Light switch conduit warm -- Why?
- 7. Center aisle -- Ramp at door not poured.
- 8. Bay 3, Sect. 6 -- Fire pump conduit needs moving.
- 9. Bay 2. Sect. 4 -- Fire hose pipe and rack needs work.
- 10. Bay 2, Sect. 3 -- Secondary safeties keep jumping off.



25X1A9a

